



PRÉCAUTIONS D'EMPLOI


Les vis doivent pénétrer de 1 cm dans l'acier.




Vis de 25




Vis de 35




Vis de 45 / 25




Vis de 45 / 35



Vis de 70 / 55 / 45 / 25




Vis de 55 / 45 / 35



Vis de 45 / 35

Vis double peau



Vis de 55 / 45 / 35